Mask Set Errata for Mask 1N52N

This report applies to mask 1N52N for these products:

- MKL28Z512VDC7
- MKL28Z512VLL7

Erratum ID	Erratum Title
e9464	FIRC: A transfer error is received when writing to the SCG_FIRCSTAT register
e9380	FlexIO: Reading FlexIO register when FlexIO functional clock is disabled results in a bus hang
e9364	LPI2C: HS-mode signal on Repeated START uses Fast mode timing for the (Repeated) START hold time
e9365	LPI2C: Master does not always end the transfer when the NACK detect flag is set
e9881	LPIT: LPIT does not stop in the Debug or Low Power modes regardless of the DBG_EN or DOZE_EN bits setting in the LPITx_MCR register when Timer Reload On Trigger is set.
e10180	SCG: Clock switch may hang if SCG_RCCR is written to the switch system clock source with a different divide ratio while an external reset is asserted
e10181	SCG: Only clearing the SOSCEN bit of the SCG_SOSCCSR register cannot disable the SOSC analog circuit

Table 1. Errata and Information Summary

Revision	Changes
14APR2016	Initial release



e9464: FIRC: A transfer error is received when writing to the SCG_FIRCSTAT register

Description: When writing to the SCG_FIRCSTAT register, a transfer error occurs that causes the code execution to stall at the write point. The SCG_FIRCSTAT register is used to trim FIRC, which is already trimmed at the factory.

Workaround: Do not use the SCG_FIRCSTAT register to trim FIRC as it is already trimmed at the factory.

e9380: FlexIO: Reading FlexIO register when FlexIO functional clock is disabled results in a bus hang

Description: Accessing a FlexIO register when the FlexIO functional clock is disabled (the clock source configured to 0 in PCC_FLEXIO0[PCS], or the selected clock source is disabled) will hang the bus and the access will stall forever.

Workaround: Always enable the FlexIO functional clock before accessing any FlexIO register.

e9364: LPI2C: HS-mode signal on Repeated START uses Fast mode timing for the (Repeated) START hold time

- **Description:** The internal HS-mode signal on Repeated START updates after the (Repeated) START hold time, which causes the (Repeated) START hold time to use the Fast mode timing in LPI2Cx_MCCR0 instead of the HS-mode timing in LPI2Cx_MCCR1. This action only affects the (Repeated) START hold time and only on a Repeated START, that initiates HS-mode. It does not affect the subsequent HS-mode data transfer. This issue occurs when the first START is at the normal speed and the second START is in the HS-mode.
- Workaround: This issue only lengthens a hold time delay in HS mode and does not affect the HS mode protocol.

e9365: LPI2C: Master does not always end the transfer when the NACK detect flag is set

- **Description:** When the NACK detect flag is set, the LPI2C master should terminate the existing transfer and block a new transfer until the flag clears. However, when the NACK detect flag is set, and a Repeated START is queued as the next operation, then the LPI2C Master does not terminate the transfer and instead continues the transfer until a STOP condition is sent. This satisfies the requirement of the I2C specification, but does not halt the transfer when it detects an unexpected NACK.
- Workaround: Confirm that both the NACK detect flag (NDF) and the end packet flag (EPF) in the LPI2Cx_MSR register are set before clearing the NACK detect flag. When both flags are set, write a STOP condition generation command (0x3FF) to the Transmit Data register and then clear the flags.

e9881: LPIT: LPIT does not stop in the Debug or Low Power modes regardless of the DBG_EN or DOZE_EN bits setting in the LPITx_MCR register when Timer Reload On Trigger is set.

- **Description:** LPIT does not stop in the Debug or Low Power modes regardless of the DBG_EN or DOZE_EN bits setting in the LPITx_MCR register when Timer Reload On Trigger is set. For example, the LPIT reloading operation occurs in the Debug mode on every rise edge of the trigger signal when setting LPITx_MCR[DBG_EN] = 0. The LPIT reloading operation also occurs in the WAIT/STOP/VLPS mode on a trigger event when LPITx_MCR[DOZE_EN] = 0.
- **Workaround:** Gate off the LPIT functional clock by clearing the PCC_LPIT0[PCS] bit just before entering the debug mode when LPITx_MCR[DBG_EN] = 0 and/or before entering the low power mode when LPITx_MCR[DOZE_EN] = 0.

For example, to stop LPIT in debug mode perform the following steps in the debugger.

1. Clear PCC_LPIT0 [PCS] in the Debugger Register window to gate off the LPIT functional clock when the code stops at a breakpoint.

2. Resume the normal debug operation.

To stop LPIT in WAIT/STOP/VLPS modes, add a code line to clear PCC_LPIT0 [PCS] to gate off the LPIT functional clock prior to entering these low power modes.

e10180: SCG: Clock switch may hang if SCG_RCCR is written to the switch system clock source with a different divide ratio while an external reset is asserted

Description: SCG: Clock switch may hang if SCG_RCCR is written to the switch system clock source with a different divide ratio while an external reset is asserted. For example, if SCG is in the FIRC mode and then configured to the SIRC mode,by writing the RCCR to switch system clock with a different divide ratio, during which the external reset is asserting, then the clock switch may hang.

Workaround: To recover the clock switch another reset must be issued.

e10181: SCG: Only clearing the SOSCEN bit of the SCG_SOSCCSR register cannot disable the SOSC analog circuit

- **Description:** When SOSC is stable (after 4096 cycles) in crystal mode, only clearing the SOSCEN bit of the SCG_SOSCCSR register cannot disable the SOSC analog circuit. This may cause clock output unstable especially when switching from a low gain mode to a high gain mode.
- **Workaround:** In the high gain mode, clearing both the SOSCEN and EREFS bits can disable SOSC digital and analog circuit within two crystal clocks.
 - In the low gain mode:
 - 1. Switch to the high gain mode.
 - 2. Wait for some time.
 - 3. Recommend at least 8 NOP instructions to ensure that the crystal clock is stable.

4. Clear both the SOSCEN and EREFS bits to disable SOSC digital and analog circuit within two crystal clocks.

Mask Set Errata for Mask 1N52N, Rev. 14APR2016

How to Reach Us:

Home Page: nxp.com Web Support: nxp.com/support Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: <u>nxp.com/SalesTermsandConditions</u>.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, Freescale, the Freescale logo, and Kinetis are trademarks of NXP B.V. All other product or service names are the property of their respective owners. ARM, the ARM Powered logo, and Cortex are registered trademarks of ARM Limited (or its subsidiaries) in the EU and/or elsewhere. mbed is a trademark of ARM Limited (or its subsidiaries) in the EU and/or elsewhere. All rights reserved.

All rights reserved.

© 2016 NXP B.V.

Document Number: KINETIS_L_1N52N Rev. 14APR2016



